02910.000122 JUL 1 0 2006 W

AC#

<u>PATENT</u>

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)	•
	:	Examiner: Patrick H. Mackey
DAISAKU KAMIYA ET AL.)	
	:	Group Art Unit: 3651
Appl. No.: 10/784,950)	
	•	Confirmation No.: 8479
Filed: February 25, 2004)	
	:	
For: SHEET STACKING/ALIGNING)	
APPARATUS, SHEET HANDLING	:	
APPARATUS, AND IMAGE FORMING)	
APPARATUS	:	
)	
U.S. Patent No.: 7,007,948 B2	:	•
)	
Issued: March 7, 2006	•	Inly 10, 2006

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450 of Correction

CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

07/12/2006 RMEBRAHT 00000023 7007948 01 FC:1811

JUL 13 2006

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

Patentees' undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

Lawrence A. Stahl Attorney for Patentees Registration No. 30,110

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200

LAS:eyw

CERTIFICATE OF CORRECTION

PATENT NO. :

7,007,948 B2

DATED

March 7, 2006

INVENTOR(S) :

DAISAKU KAMIYA ET AL.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COVER PAGE AT ITEM [56] RC:

Foreign Patent Documents, "2002179322 A" should read --2002-179322 A--; and "2003335449 A" should read --2003-335449 A--.

COLUMN 1:

Line 18, "a" (1st occurrence) should read --an--.

COLUMN 2:

Line 54, "operation" should read --operations--.

Line 55, "handing" should read --handling--.

COLUMN 5:

Line 20, "is" should be deleted.

Line 63, "till" should read --until--.

COLUMN 6:

Line 23, "are" should read --is--.

Line 26, "are" should read --is--.

Line 48, "till" should read --until--.

COLUMN 7:

Line 20, "are" should read --is--.

Line 27, "sheets" should read --sheet--.

Line 32, "turning" should read --turn--.

COLUMN 8:

Line 48, "face 9a" should read -- face 4a--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) (Form#30)

PATENT NO. <u>7,007,948 B2</u>

No. of add'l. copies @ 30¢ per page



JUL 13 ZUUb

CERTIFICATE OF CORRECTION

PATENT NO.

7,007,948 B2

DATED

March 7, 2006

INVENTOR(S) :

DAISAKU KAMIYA ET AL.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 9:

Line 7, "unit 60," should read --unit 360,--.

COLUMN 11:

Line 10, "bundle." should read --bundle--.

Line 57, "wail" should read --wall--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) (Form#30)

PATENT NO. 7,007,948 B2

No. of add'l. copies @ 30¢ per page

 \Rightarrow

JUL 13 4006

CERTIFICATE OF CORRECTION

PATENT NO. :

7,007,948 B2

DATED

March 7, 2006

INVENTOR(S) :

DAISAKU KAMIYA ET AL.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COVER PAGE AT ITEM [56] RC:

Foreign Patent Documents, "2002179322 A" should read --2002-179322 A--; and "2003335449 A" should read --2003-335449 A--.

COLUMN 1:

Line 18, "a" (1st occurrence) should read --an--.

COLUMN 2:

Line 54, "operation" should read --operations--.

Line 55, "handing" should read --handling--.

COLUMN 5:

Line 20, "is" should be deleted.

Line 63, "till" should read --until--.

COLUMN 6:

Line 23, "are" should read --is--.

Line 26, "are" should read --is--.

Line 48, "till" should read --until--.

COLUMN 7:

Line 20, "are" should read --is--.

Line 27, "sheets" should read --sheet--.

Line 32, "turning" should read --turn--.

COLUMN 8:

Line 48, "face 9a" should read -- face 4a--.

MAILING ADDRESS OF SENDER:


FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) (Form#30)

PATENT NO. <u>7,007,948 B2</u>

No. of add'l. copies @ 30¢ per page



CERTIFICATE OF CORRECTION

PATENT NO. :

7,007,948 B2

DATED

March 7, 2006

INVENTOR(S) :

DAISAKU KAMIYA ET AL.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 9:

Line 7, "unit 60," should read --unit 360,--.

COLUMN 11:

Line 10, "bundle." should read --bundle--. Line 57, "wail" should read --wall--.

DC_MAIN 246145v1

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) (Form#30)

PATENT NO. 7,007,948 B2

No. of add'l. copies @ 30¢ per page

